

**ATTACHMENT B
TO
OCCIDENTAL COMMENTS
REGARDING
NATURAL RESOURCE TRUSTEES
"SETTLEMENT REPORT"**

INDEX TO VOLUMES I THROUGH XVII:

Volume I

Occidental Comments and Attachments
Attachment A - Site Maps
Attachment B - Index to Volumes I through XVII
Attachment C - CD-ROM Data
Figures 1 – 8
Table 1

Volume II

Site 56 Data (May 1998) (CRA: Field Activities and Data Report)
Site 56 Data – Volumes I and II (October 1998) (Hart Crowser: Pre-Remedial Design Study)
PCB "Fingerprinting" in Mouth (Affidavit of Alan F. Weston Regarding PCB Distributions on the Embankment and in the Sediments at the Mouth of the Hylebos Waterway)

Volume III

Site 59 Data (June 2001) (Anchor and CRA: Navy Bank Surface Sediment Characterization Data Report)
Site 60 Data (February 1998) (Hart Crowser: Memorandum regarding Parcel 4 Investigation)

Volume IV

Site 41 Data (October 2000) (Anchor: Sound Refining Mudflat Area Focused Site Characterization Data Report)
Segments 3 & 4 Data (October 2001)(Anchor: Hylebos Segments 3 and 4 Supplemental Data Report, Phase I Hylebos Mouth Cleanup)

Volume V

National Archives Report, Navy/Todd Shipyard, Hylebos Mouth Area (Report and Maps 1-13)

Volume VI

National Archives Report, Exhibits 1 - 5

Volume VII

National Archives Report, Exhibits 6 - 53

Volume VIII

National Archives Report, Exhibits 54 - 75

Volume IX

National Archives Report, Exhibits 76 - 113

Volume X

National Archives Report, Exhibits 114 - 153

Volume XI

National Archives Report, Exhibits 154 – 168

Volume XII

Ship Building, Maintenance & Dismantling
Hazardous Substances (PCBs, PAHs, Metals, etc.)
Indexes of World War II Ship Components
Historical Photographs and Real Estate Records of Site 56 Operations
Ships Built by Navy/Todd
 Contamination of Oxy's "North Ten Acres" (Navy/Todd Dump)
 "North Ten Acres" Real Estate Record
 Zidell Dismantling Activities
Newspaper Articles regarding Site 56
Navy Ship Moorage at Site 57 (PRI)

Volume XIII

104(e) Responses -- U.S. Navy, Todd Shipyards, Port of Tacoma,
and Zidell Dismantling

Volume XIV

Zidell Dismantling and AK-WA Shipbuilding Documents from
Ecology and EPA

Volume XV

Hazardous Substances in Ships

Navy Reports regarding PCBs in Navy Vessels

PCBs in Navy Vessels -- USS Cabot/Dedalo Museum Foundation, et al.
v. U.S. Customs Service

EPA Shipyard Guidelines

PCBs and Metals Detected in Site 56 Storm Sewers

Navy Ship Dismantling -- Environmental Problems

Baltimore Sun Articles

Congressional Hearings

Interagency Panel on Ship Scrapping

Volume XVI

Other Shipyards (PCBs, PAHs, Metals, etc.)

Puget Sound Manchester Annex

Norfolk Naval Shipyards

Ecology Complaints regarding Navy Fuel and Oil Spills in Puget Sound

Volume XVII

Approval of Site 57 Discharges by Ecology

Site 57 Discharge Permits

Site 19 Sampling Data (AWARE Report, November 1981)

Site 19 Ecology Analytical Results (June 1981)

Site 19 EPA Analytical Results (April 1984)

Site 47 Analytical Data (July 1991) (Burlington Environmental)